
Potentiometer Geared limit switches Potentiometer Getriebeendschalter

MICRONOR automation components

Serie DWG 120



•	Widerstandwerte	100R100K (Ω)
	Resistance	
•	Programmkanäle (einstellbar)	2 + 3
	Program channel (free setting)	
•	Eingangsübersetzungen	1:12500 : 1
	Input ratios	
•	Mikroschalter	4A 250V AC 1A 60V DC
	Snap action switches	
•	Schutzart	IP 64
	Protection	

Application:

- Motorized potentiometers are basically the best in the field of control and regulation technics
- The possibility to mount several potentiometers on the same shaft allows also a remote display of the position of the potentiometer
- Supplementary cams can be used to give limit signals depending on the position of the potentiometer
- Supplementary cams can also be used to offset a residual resistance of the potentiometer at the zero point
- One supplementary cam can be used as zero point interlocking

s = 8,5


Design:

- High precision wire-wound potentiometer with high resolution and linearity
- Potentiometer directly driven by the cam shaft
- Two adjustable limit switches controlling the rotation angle of the potentiometer
- Solid mechanical Stopps preventing damage to potentiometers
- Available with AC or DC motors
- Friction clutch protecting the unit when manually operated
- The modular design allows quick delivery practically without delay, voltage resistance and cycle time according to your requirements

Outline drawing

ød = 9-h8

MS = Montagefläche / Mounting surface



Serie DWG 120

				DWG120	2	U1	
Alu-diecasting / Colour (RAL 7001 grey)							
Size (mm) / Number of switches:							
Dimension: 2							
2 Switches							
= 2 Adjustable limit switches (NK4101.20°)							
0 Program channels (free setting) (NK4201)							
Knob and scale SK100 (0100%)							
Dimension: 3							
3 Switches							
= 2 Adjustable limit switches (NK4101.20°)							
1 Program channels (free setting) (NK4201)							
1 Program key (PSN)							
Knob and scale SK100 (0100%)							
Knob and scale SK100 (0100%)	e stage; M = more	stage					
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on		stage =	12.5:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on J1 = 1:1	e stage: M = more M1 M2		12,5:1 20:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on J1 = 1:1 J2 = 1,25:1	M1	=					
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on J1 = 1:1 J2 = 1,25:1 J3 = 1,5:1	M1 M2	= =	20:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on J1 = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1	M1 M2 M3	= = =	20:1 25:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on J1 = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1 J5 = 2,6:1	M1 M2 M3 M4	= = =	20:1 25:1 37,5:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on J1 = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1 J5 = 2,6:1 J6 = 2,75:1	M1 M2 M3 M4 M5	= = = =	20:1 25:1 37,5:1 40:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on J1 = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1 J5 = 2,6:1 J6 = 2,75:1 J7 = 3,5:1	M1 M2 M3 M4 M5 M6	= = = =	20:1 25:1 37,5:1 40:1 52,5:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on JI = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1 J5 = 2,6:1 J6 = 2,75:1 J7 = 3,5:1 J8 = 4:1 J9 = 5:1	M1 M2 M3 M4 M5 M6 M7	= = = =	20:1 25:1 37,5:1 40:1 52,5:1 75:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on JI = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1 J5 = 2,6:1 J6 = 2,75:1 J7 = 3,5:1 J8 = 4:1 J9 = 5:1	M1 M2 M4 M5 M6 M7 M8	= = = = =	20:1 25:1 37,5:1 40:1 52,5:1 75:1 100:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on JI = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1 J5 = 2,6:1 J6 = 2,75:1 J7 = 3,5:1 J8 = 4:1 J9 = 5:1	M1 M2 M3 M5 M6 M7 M8 M9 M10 M11	= = = = =	20:1 25:1 37,5:1 40:1 52,5:1 75:1 100:1 200:1 300:1 420:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on JI = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1 J5 = 2,6:1 J6 = 2,75:1 J7 = 3,5:1 J8 = 4:1 J9 = 5:1	M1 M2 M3 M4 M5 M6 M7 M8 M9 M10 M11 M12		20:1 25:1 37,5:1 40:1 52,5:1 75:1 100:1 200:1 300:1 420:1 600:1				
Knob and scale SK100 (0100%) put ratios (Shaft to switches + Potentiometer):> U = on JI = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1 J5 = 2,6:1 J6 = 2,75:1 J7 = 3,5:1 J8 = 4:1 J9 = 5:1	M1 M2 M3 M4 M5 M6 M7 M8 M9 M10 M11 M12 M13		20:1 25:1 37,5:1 40:1 52,5:1 75:1 100:1 200:1 300:1 420:1 600:1 750:1				
Knob and scale SK100 (0100%) uput ratios (Shaft to switches + Potentiometer):> U = on JI = 1:1 J2 = 1,25:1 J3 = 1,5:1 J4 = 2:1 J5 = 2,6:1 J6 = 2,75:1 J7 = 3,5:1 J8 = 4:1 J9 = 5:1	M1 M2 M3 M4 M5 M6 M7 M8 M9 M10 M11 M12 M13 M14		20:1 25:1 37,5:1 40:1 52,5:1 75:1 100:1 200:1 300:1 420:1 600:1 750:1 1200:1				
	M1 M2 M3 M4 M5 M6 M7 M8 M9 M10 M11 M12 M13		20:1 25:1 37,5:1 40:1 52,5:1 75:1 100:1 200:1 300:1 420:1 600:1 750:1				

1	= 200Ω	6	=	10KΩ	
2	= 500Ω	7	=	100Ω	On request
3	= 1KΩ	8	=	20KΩ	On request
4	= 2KΩ	9	=	100KΩ	On request
5	= 5KΩ				