



For Thomson Micron replacements, order:
R11WF103

Related Items:

- R11BHW50FF533 replaces Micron 73-206-879 / Clifton 11-BHW-50F/F533B
- R11XJ107 replaces Micron 73-206-879 / Harowe 11BRCX-300-J95C

For additional technical information, contact Micronor and request:

- MICRON Replacement Position Transducers Data Sheet

MICRONOR INC.

750 Mitchell Road
Newbury Park, CA 91320
United States of America
T +1-805-499-0114
F +1-805-499-6585
sales@micronor.com
www.micronor.com

MICRONOR AG

Pumpwerkstrasse 32
CH-8105 Regensdorf
Switzerland
T +41-44-843-4020
F +41-44-843-4039
sales@micronor.ch
www.micronor.com